

Qwik Tees and Ells

For in-wall or other limited space connections

To Repair Or Replace A Plastic Ell Or Tee

To repair this installed rigid elbow it is first necessary to cut out the elbow. After cutting the portion of pipe that was welded into each socket is lost and now a regular schedule 40 fitting can no longer be used in replacement unless the pipes are extended back to normal position. Also, the pipes are usually in a fixed position, making it difficult or impossible to get the necessary room required to solvent weld a new joint. The Qwik Elbows and Qwik Tees, however, are engineered with extra length and flexibility to compensate for the shortened pipes.

